

CERTIFICATE OF COMPLIANCE

Certificate Number 20190308-E302724
Report Reference E302724-A87-UL
Issue Date 2019-MARCH-08

Issued to: CRESTRON ELECTRONICS INC
15 VOLVO DR, ROCKLEIGH NJ 07647-2507

**This certificate confirms that
representative samples of**

AUDIO/VIDEO APPARATUS

Audio Signal Processor: DSP-860, DSP-1280, DSP-1281, DSP-1282, DSP-1283, M201907001

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.


Standard(s) for Safety: UL 60065 and CAN/CSA-C22.2 No. 60065-03- Audio, video and
similar electronic apparatus - Safety requirements

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

